

0007

From: Steve Demczak
To: Angela Nance; Vicky Miller
Date: 12/7/2009 11:03 AM
Subject: Nov Insp Report
Attachments: 20091207111745.pdf; 20091207111808.pdf; 20091207111721.pdf

Outgoing

C0070018

C0070039

C0070034

&



State of Utah

Department of Natural Resources

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA
Division Director

JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

Representatives Present During the Inspection:

Company Vicky S. Miller Environmental Specialist

OGM Steve Demczak Environmental Scientist III

Inspection Report

Permit Number:	C0070018
Inspection Type:	COMPLETE
Inspection Date:	Monday, November 16, 2009
Start Date/Time:	11/16/2009 10:00:00 AM
End Date/Time:	11/16/2009 12:00:00 PM
Last Inspection:	Tuesday, August 18, 2009

Inspector: Steve Demczak, Environmental Scientist III

Weather: Sunny, cold 30's

InspectionID Report Number: 2202

Accepted by: jhelfric

12/7/2009

Permittee: **CANYON FUEL COMPANY LLC**

Operator: **CANYON FUEL COMPANY LLC**

Site: **SOLDIER CANYON MINE**

Address: **PO BOX 1029, WELLINGTON UT 84542**

County: **CARBON**

Permit Type: **PERMANENT COAL PROGRAM**

Permit Status: **ACTIVE**

Current Acreages

6,624.64	Total Permitted
24.32	Total Disturbed
	Phase I
	Phase II
	Phase III

Mineral Ownership

- ☒ Federal
☒ State
☐ County
☐ Fee
☐ Other

Types of Operations

- ☒ Underground
☐ Surface
☐ Loadout
☐ Processing
☐ Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Permit Condition: Canyon Fuel Company has just one permit condition for the Soldier Canyon Mine; to submit water quality data in an electronic format through the Electronic Data Input web site.

Permitting Actions: None

Inspector's Signature:


Steve Demczak, Environmental Scientist III

Inspector ID Number: 39

Date Thursday, November 19, 2009

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

1594 West North Temple, Suite 1210, PO Box 145801, Salt Lake City, UT 84114-5801
telephone (801) 538-5340 • facsimile (801) 359-3940 • TTY (801) 538-7458 • www.ogm.utah.gov

Permit Number: C0070018
 Inspection Type: COMPLETE
 Inspection Date: Monday, November 16, 2009

Inspection Continuation Sheet

Page 2 of 4

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
19. AVS Check	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
22. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

1. Permits, Change, Transfer, Renewal, Sale

No permitting action is with the Division for Soldier Creek Mine. The permit will expire on Feb. 12, 2012. The SPPC plan was last inspected on December 3, 2007. The UPDES permit will expire on March 31, 2011. SPCC Plan was reviewed on 12/03/2007 by a P.E..

2. Signs and Markers

Identification signs are at gates to the property.

3. Topsoil

There were no signs of wind or water erosion.

4.a Hydrologic Balance: Diversions

Diversions were inspected and would function during a storm event.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

The sediment pond was inspected for the second quarter on August 17, 2009. No hazardous conditions were reported. I inspected the sediment pond and no hazardous conditions were not noticed.

4.e Hydrologic Balance: Effluent Limitations

No discharge for the third quarter of 2009.

8. Noncoal Waste

The site was cleaned up last summer.

10. Slides and Other Damage

No slides or other damage was noticed during the inspection.

15. Cessation of Operations

The mine site is still in cessation.

16.a Roads: Construction, Maintenance, Surfacing

Concrete has started to break-up in several places.

16.b Roads: Drainage Controls

Road drainage is functioning.

18. Support Facilities, Utility Installations

No new facilities constructed since last inspection.

Permit Number: C0070018
Inspection Type: COMPLETE
Inspection Date: Monday, November 16, 2009

Inspection Continuation Sheet

Page 4 of 4

20. Air Quality Permit

DAQE-334-94

21. Bonding and Insurance

The insurance policy will expire on June 31, 2010. The bonding amount is \$1,593,000



State of Utah

Department of Natural Resources

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA
Division Director

JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

Representatives Present During the Inspection:

Company	Vicky S. Miller	Environmental Specialist
OGM	Steve Demczak	Environmental Scientist III

Inspection Report

Permit Number:	C0070039
Inspection Type:	COMPLETE
Inspection Date:	Thursday, November 12, 2009
Start Date/Time:	11/12/2009 10:00:00 AM
End Date/Time:	11/12/2009 2:00:00 PM
Last Inspection:	Wednesday, October 07, 2009

Inspector: Steve Demczak, Environmental Scientist III

Weather: Sunny, 50's

InspectionID Report Number: 2200

Accepted by: jhelfric

12/7/2009

Permittee: **CANYON FUEL COMPANY LLC**

Operator: **CANYON FUEL COMPANY LLC**

Site: **DUGOUT CANYON MINE**

Address: **PO BOX 1029, WELLINGTON UT 84542**

County: **CARBON**

Permit Type: **PERMANENT COAL PROGRAM**

Permit Status: **ACTIVE**

Current Acreages

9,751.00	Total Permitted
104.70	Total Disturbed
	Phase I
	Phase II
	Phase III

Mineral Ownership

- ☒ Federal
☒ State
☐ County
☒ Fee
☐ Other

Types of Operations

- ☒ Underground
☐ Surface
☐ Loadout
☐ Processing
☐ Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

There are no pending compliance actions for the Dugout Canyon Mine permit area.

The Permittee is current relative to the required electronic quarterly water monitoring submittals for 2009.

Inspector's Signature: _____

Steve Demczak, Environmental Scientist III

Inspector ID Number: 39

Date Thursday, November 19, 2009

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

1594 West North Temple, Suite 1210, PO Box 145801, Salt Lake City, UT 84114-5801
telephone (801) 538-5340 • facsimile (801) 359-3940 • TTY (801) 538-7458 • www.ogm.utah.gov

Permit Number: C0070039
 Inspection Type: COMPLETE
 Inspection Date: Thursday, November 12, 2009

Inspection Continuation Sheet

Page 2 of 4

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
19. AVS Check	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
22. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

1. Permits, Change, Transfer, Renewal, Sale

DOGM Permit will expire on March 17, 2013. Air Quality permit number is DAQUE-AN0116340009-07. UPDES permit number is UT0025593 and expire on Nov. 30, 2009. The SPCC Plan was reviewed on March 14, 2008.

2. Signs and Markers

The permit sign is located at the gate to the property. Information meets the minimum requirements of the R645 Coal Rules.

3. Topsoil

The topsoil pile next to the refuse pile were inspected. There is some vegetated growth which includes some weeds. There were no signs of wind or water erosion to the piles.

4.a Hydrologic Balance: Diversions

The diversions were spot inspected and were functioning as designed.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

I inspected the sediment pond; and it did contain water but was not discharging during the inspection. The pond was cleaned out a few of months ago. No hazardous conditions were noticed during the inspection. The sediment pond was inspected on June 30, 2009 by the permittee.

4.d Hydrologic Balance: Water Monitoring

The permittee has sent the second quarter water data to the Division.

7. Coal Mine Waste, Refuse Piles, Impoundments

The waste rock site was inspected with no hazardous conditions noticed during the inspection. The permittee inspected the refuse pile on Aug 12, 2009. This was conducted by a P.E.. No hazardous conditions were reported.

8. Noncoal Waste

The mine site was clear of non-coal waste materials.

10. Slides and Other Damage

No slides or other damage was noticed during the inspection.

14. Subsidence Control

This information is in the annual report.

16.b Roads: Drainage Controls

Road diversions were inspected and were functioning as designed.

Permit Number: C0070039
Inspection Type: COMPLETE
Inspection Date: Thursday, November 12, 2009

Inspection Continuation Sheet

Page 4 of 4

18. Support Facilities, Utility Installations

No new facilities constructed since the last inspection.

21. Bonding and Insurance

The insurance policy will expire on July 31, 2010. The accord form was reviewed and meets the requirements of the R645 Coal Rules. The bonding amount is \$3,550,000. The Reclamation Agreement was inspected and is signed by the Division. The total disturb area is 104.70 acres.



State of Utah

Department of Natural Resources

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA
Division Director

JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

Representatives Present During the Inspection:

Company	Vicky S. Miller	Environmental Specialist
OGM	Steve Demczak	Environmental Scientist III

Inspection Report

Permit Number:	C0070034
Inspection Type:	COMPLETE
Inspection Date:	Thursday, November 19, 2009
Start Date/Time:	11/19/2009 12:00:00 PM
End Date/Time:	11/19/2009 2:00:00 PM
Last Inspection:	Tuesday, August 18, 2009

Inspector: Steve Demczak, Environmental Scientist III

Weather: Sunny, cold, 30's

Inspection/ID Report Number: 2203

Accepted by: jhelfric
12/7/2009

Permitee: **CANYON FUEL COMPANY LLC**

Operator: **CANYON FUEL COMPANY LLC**

Site: **BANNING SIDING LOADOUT**

Address: **PO BOX 1029, WELLINGTON UT 84542**

County: **CARBON**

Permit Type: **PERMANENT COAL PROGRAM**

Permit Status: **ACTIVE**

Current Acreages

36.42	Total Permitted
21.60	Total Disturbed
	Phase I
	Phase II
	Phase III

Mineral Ownership

- ☒ Federal
☒ State
☐ County
☒ Fee
☐ Other

Types of Operations

- ☐ Underground
☐ Surface
☐ Loadout
☐ Processing
☐ Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Permit Condition: Canyon Fuel Company has just one permit condition for the Banning Loadout; to submit water quality data in an electronic format through the Electronic Data Input web site.

Inspector's Signature: _____

Steve Demczak, Environmental Scientist III

Inspector ID Number: 39

Date Thursday, November 19, 2009

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

1594 West North Temple, Suite 1210, PO Box 145801, Salt Lake City, UT 84114-5801
telephone (801) 538-5340 • facsimile (801) 359-3940 • TTY (801) 538-7458 • www.ogm.utah.gov

Permit Number: C0070034
 Inspection Type: COMPLETE
 Inspection Date: Thursday, November 19, 2009

Inspection Continuation Sheet

Page 2 of 3

REVIEW OF PERMIT PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
19. AVS Check	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
22. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

1. Permits, Change, Transfer, Renewal, Sale

here are no permitting actions with the Division. The permit will expire on 11/24/2013. The SPCC Plan was reviewed on December 3, 2007.

2. Signs and Markers

The identification signs is at the gate to the property.

4.a Hydrologic Balance: Diversions

Diversions were functioning as designed. The ditches were not flowing water.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

The sediment pond did not discharge for the third quarter of 2009. I inspected the sediment pond and did not see any hazardous conditions. The permittee inspected the sediment pond on August 17, 2009. No hazardous conditions were reported.

8. Noncoal Waste

The disturb area was clear of non-coal waste materials.

10. Slides and Other Damage

No slides or other damage was noticed during the inspection.

15. Cessation of Operations

This site is not active.

16.b Roads: Drainage Controls

Road drainage is functioning.

18. Support Facilities, Utility Installations

There are no new facilities.

20. Air Quality Permit

Air Quality Permit number is 533-6108

21. Bonding and Insurance

The insurance policy will expire on July 31, 2010. The bonding amount is \$350,000.